

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM <b>Winchester Electronic, Inc.</b>										DATE REC'D <b>1-31-57</b> P.O. NO. <b>69110</b> VENDOR PACKING SLIP NO.	
CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.	
25	322	000000	10147	0	0	00	00	02		S.O. NO.	
DRAWING NO. AND DESCRIPTION						QUANTITY		REMARKS			
						ACCEPTED	REJECTED				
Connector Winchester A7-PLIN 730163-78						15	✓				
								<i>H. P. Gandy</i> <i>J. P. Gandy</i>			

RECEIVED BY *J. P. Gandy* INSPECTED BY *Dura* DATE **2/4/57** REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11132

RECEIVED FROM <b>Aviation Developments Inc.</b>										DATE REC'D <b>2-1-57</b> P.O. NO. <b>69096</b> VENDOR PACKING SLIP NO. <b>29-95</b>	
CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.	
12	322	000020	10110	0	0	00	00	02		S.O. NO.	
DRAWING NO. AND DESCRIPTION						QUANTITY		REMARKS			
						ACCEPTED	REJECTED				
730157-11 Pin, 719 A-414 Part 5						12	✓				
								<i>H. P. Gandy</i> <i>J. P. Gandy</i>			

RECEIVED BY *J. P. Gandy* INSPECTED BY *Dura* DATE **2/1/57** REJECTS RETURNED ON SHIP. MEMO NO.